



Step 1. Attach cross bars to round counter legs, tighten using **5mm hex key**.



Step 3. Attach counter to support using **2" long 1/4"-20 button head screw**, tighten using **5/32" (4mm) hex key**.



Step 2. Attach support to column, tighten using **5mm hex key**.

