

Step 1. Attach lower column to base using two **short** knobs; attach gusset caps.



Step 2. Attach upper column to lower column; tighten two **short** knobs.



Step 3. Attach v legs to counter top using two **long** knobs.




Step 4. Attach counter assembly to lower column using three **long** knobs; install infill panel. (Attach optional lower shelf to lower column using one **long** knob.)



Step 5. Slide on canopy support; tighten **short** knob.



Step 6. Assemble canopy using two **long** knobs per extrusion. Install plex and lights. Attach standoffs.



Step 7. Attach canopy to upper column using one **long** knob.



Step 8. Attach wings using **nylon tipped** knobs. Attach header using standoffs.

